



SS SCREW DISPLAY

Includes Display Board, Pegs and 45 packages of Hardware



Packaged Screws For "SS" Display

50 ea. 6 x 1/2 PTA
8 x 1/2
10 x 1/2

25 ea. #8 Flat Washer
#10 Flat Washer

50 ea. 632 x 1/2 PFMS
832 x 1/2
1032 x 1/2

50 ea. 632 x 1/2 PTMS
832 x 1/2
1032 x 1/2

50 ea. 6 x 1/2 PFA
8 x 1/2

25 ea. #8 Tinnerman Washer
#10 Tinnerman Washer

Other sizes for SS Display or for your own peg board display area

Screws 50 pc. packs — Lock nuts 25 pc. packs

PHILLIPS TRUSS TYPE "A"

4 x 3/8 PTA
4 x 1/2
6 x 3/8
6 x 5/8
8 x 3/8
8 x 5/8
8 x 3/4
10 x 5/8
10 x 3/4

PHILLIPS TRUSS MACHINE SCREW

632 x 3/8 PTMS
632 x 5/8
632 x 3/4
832 x 3/8
832 x 5/8
832 x 3/4
1032 x 3/8
1032 x 5/8
1032 x 3/4

PHILLIPS FLAT TYPE "A"

4 x 3/8 PFA
4 x 1/2
6 x 3/8
6 x 5/8
8 x 5/8
8 x 3/4
10 x 1/2
10 x 5/8
10 x 3/4

PHILLIPS FLAT MACHINE SCREW

632 x 3/8 PFMS
632 x 5/8
832 x 3/8
832 x 3/4
1032 x 5/8
1032 x 3/4
632 Locknut
832 Locknut
1032 Locknut

© 2001 Trimcraft Aviation

TRIMCRAFT AVIATION, INC. • P.O. Box 488 • Genoa City, WI 53128

1-800-558-9405

FAX 262-279-3350